## C.NO/217/ADV/CFO/HBL/2020

To,

The Secretary, Sri Venkateshwar Education Trust, Annigeri, Dharwad District.

## Sir,

Sub : Issue of '*Fire safety recommendation/Advice'* Sri Sharada English Medium School, Sy.No.15/2, Gadag Road, NH-63, Annigeri, Dharwad District.

1

With reference to the subject above cited, the premises of Sri Sharada English Medium School building with 3 blocks consisting with ground floor only situated at Sy.No.15/2, Gadag Road, NH-63, Annigeri, Dharwad District was inspected by the District Fire Officer, Hubballi Amargol on 14/12/2020 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

## ANNEXURE-B

## "B1& B2 – Schools upto senior secondary level and other institutions" NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings

(These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

A. Details of the building / premises :-

01	Name and Address of the Applicant.	:	The Secretary, Sri Venkateshwar Education Trust, Annigeri, Dharwad District
02	Name and Address of the premises.	:	Sri Sharada English Medium School Sy.No.15/2, Gadag Road, NH-63, Annigeri, Dharwad District
03	Name and address of the Building owner	1	The Secretary, Sri Venkateshwar Education Trust, Annigeri, Dharwad District
04	Number of buildings	10	03

OFFICE OF THE CHIEF FIRE OFFICER Karnataka State Fire and Emergency Services, Date 1440/2120205.

05	Number of floors	:	Administrations Building -Ground Floor School building-Ground Floor Library & Canteen Area-Ground Floor		
06	Floor-wise details of occupancy:-				
	Administrations Building Ground floor	:	Proposed to VIP Meeting Hall, Staff Room, 2 VIP Hall, Principal Room, Reception, committee Hall, Secretary & Chairman Room.		
	School Building Ground floor	:	20 nos. of Class room, Gents Principal Room, 1 Ladies Principal Room, 2 Ladies Staff Room & rest Room.		
	Library & Canteen Building Ground floor	:	Proposed to 01 Canteen & Library.		
07	Height of the building	:	Administrations Building -04.50 mtrs. School building-4.55 mtrs. Library & Canteen Area-4.50 mtrs.		
08	Site area	:	12144.98 Sq. Mtrs.		
09	Built-up area of each floor:-				
	Administrations Building Ground floor	:	1087.22 Sq. Mtrs.		
	School Building Ground floor	:	2238.47 Sq. Mtrs.		
014	Library & Canteen Building Ground floor	:	610.68 Sq.Mtrs.		
10.	Total built-up area	:	3936.37 Sq. Mtrs.		
11.	Surrounding properties:-				
	East	:	Vacant Land		
	West	:	09.00 mtrs wide school internal road		
	North		Agriculture Land		
	South	:	Agriculture Land		
12.	Set-back area available around the building :-				
	East	:	12.00 mtrs.		
	West	:	04.50 mtrs.		
	North	:	24.51 mtrs.		
	South	:	04.50 mtrs.		

Note : Recommended to provide and maintain setbacks as per Local ZR.



2

B. On inspection of this Educational premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :

Accessibility to the premises No. of entrances Width of entry / exit		00 com bli	mtrs. wide necting the	Adequate
Width of entry /		t.		
	00.00 meters:1-	01 no. of entry & exit.		
Not required as the is low.	09.00 mtrs. wide			Adequate Minimum 06.00, mtrs. width with height clearance of minimum 05.00 mtrs. from ground level.
Diesel generators.				Recommended to provide diesel generator of adequate capacity.
No. of staircases available	Nos. of staircases Width of staircases Width of treads	:	03 2.00 mt 30 cm	Adequate
floor directing	Height of risers	:	15 cm	
	Nos. of riser per flight	:	10	
	Height of handrails	:	00.90 mt	
tabon in one of	clearance		2.50 mt	* * *
No. lifts and capacity.	Nos. of lifts Capacity of lifts	:	Nil	N/A
Fire extinguisher	01 no. of ABC Fire of 06 kg Capacity CO2 Extinguisher	&	01 no. of	Fire extinguishers required (ABC, CO <sub>2</sub> ) for every 100 sq.mtrs. built up area.
	Diesel generators. No. of staircases available No. lifts and capacity.	Diesel generators No. of staircases available Nos. of staircases Width of staircases Width of treads Height of risers Nos. of riser per flight Height of handrails Head room clearance No. lifts and capacity. Fire extinguisher O1 no. of ABC Fire of 06 kg Capacity CO2 Extinguisher	Diesel generators No. of staircases available Nos. of staircases Width of staircases Height of treads Height of risers Height of risers Height of handrails Height of handrails Head room clearance No. lifts and Nos. of lifts Head room clearance No. lifts and Nos. of lifts Fire extinguisher O1 no. of ABC Fire Ext of 06 kg Capacity & CO2 Extinguisher of	Diesel generatorsNo. of staircases availableNos. of staircases Width of staircases:03Width of staircases Width of treads:2.00 mtWidth of treads:30 cmHeight of risers:15 cmNos. of riser per flight:10Height of handrails:00.90 mtHead room clearance:2.50 mtNo. lifts and capacity.Nos. of lifts:NilFire extinguisher01 no. of ABC Fire Extinguishers of 06 kg Capacity & 01 no. of CO2 Extinguisher of 02 kg

08.	Public address system		Not required as the risk is low.
09.	First aid Hose reel hose.		Not required as the risk is low.
10.	Automatic sprinkler system.	Sea provide Tr department set I	Not required as there is no basement.
11.	Terrace tank over respective tower terrace.	Provided 2000 ltrs. capacity of terrace tank.	Terrace tank required 10,000 ltrs. Capacity for each down comer system.
12.	At the terrace tank level with minimum pressure of 3.5 kg/cm <sup>2</sup> .	 Johnne Johne (1999)	Not required as the risk is low.
13.	Fire control room at ground floor.		Not required as the risk is low.
14.	Escape routes		Recommended to Provide Direction in which the employees/ Students should have to move in the event of any emergency have been marked with luminous paint at each floor directing the employees towards emergency exits.
15.	Fire order		Fire safety plans has to be indicated with details of actions to be taken in case of an emergency near staircase landings at each floor with telephone numbers of Annigeri fire station i.e., 08380-222401 & 101 telephone numbers of the nearest Ambulance service.

16.	Fire fighting training	Not provided	At-least 40% of employees shall be got trained in basic fire fighting at R.A.Mundkur fire & Emergency Services Academy, Bannerughatta road, Bangalore within 3 months or at an early date. And shall be submitted to this office.
17.	Additional recommendations.	<ol> <li>Recommended to provided 01 kg capacity for every 04 Class Extinguisher of 05 kg capacity of CO2 Extinguisher for Store</li> <li>Recommended to provide 01 kg capacity at the Electrical P First Aid boxes at the office.</li> <li>Recommended to provide 01 electric operated siren.</li> <li>Petroleum products like LPG stored in the School Building</li> <li>An awareness program of fire conducted in your School for lectures in this regard the ma Principal of the School shoul Officer Hubli Zone.</li> <li>No thatched houses shall be e premises.</li> <li>If kitchen or canteen is provis separate building.</li> <li>Jump wires and loose connect and inflammable are prohibit</li> <li>Combustible material shall n premises.</li> <li>All the equipments shall be p the trained staff of School.</li> </ol>	srooms, 02 Nos. of ABC y to the library & 02 Nos. e room. CO2 extinguisher of 4.5 anel room And 05 nos. of No. of Emergency , Petrol, etc. shall not be e fighting and safety to be School students and magement or The Id contact the Chief fire erected in the School ded, it should be in a 5 mts. away from the ction of electric wirings ed. ot be stored in the School

The Karnataka Fire & Emergency Service Department is issued the Fire Safety recommendations in compliance to the undersigned, within 90 days.



All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.4 of Fire and Life safety will have to be complied with mandatorily.

From the above details it is clear that the 'Management' of the above Educational building have been recommended to provide fire precautionary measures as per National Building Code 2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. After full-filling the above recommendations, a Certificate should be obtained by this office. If at any time any of the conditions are found not complied with, this Certificate shall stand withdrawn/cancelled.

Hence, On the report submitted by the District Fire Officer Hubballi this recommendations is issued to Sri Sharada English Medium School building consisting of Ground floor only situated at Sy.No.15/2, Gadag Road, NH-63, Annigeri, Dharwad District.

This certificate is valid for a period of one year from the date of issue of this letter and is renewable.



Yours faithfully, Swy IN CHIEF FIRE OFFIC Karnataka State Fire and

Emergency Services, Hubballi Zone HUBBALLI-25.

Copy to the District Fire Officer, Hubballi.